



MALTA RESOURCES AUTHORITY

MRA/83/07

16th August 2011

**TENDER FOR SUPPLY OF A PRIVATE AUTOMATIC BRANCH EXCHANGE
(PABX) SYSTEM**

Question 1: Does the present PABX system include a main distribution frame (MDF)?

The current PABX system does not have a main distribution frame (MDF).

Question 2: Does the quoted PABX system have to include a new main distribution frame (MDF)?

A new main distribution frame is not mandatory. However, tenderers are reminded that "The cabling between the PABX and the patch panel should form part of the installation".